DLL Patch notes 08/AUG/2023

Description of Change:

- ubolometerDLL_V6 updated to version 22.2

Feature Improvements:

- Software corruption on start-up & recovery reduced
- Recovery software delay reduced

Reason for Change:

- Corruption events on start-up/recovery results in a complete breakdown of the instrument. The new DLL reduces occurrence of the event.